


Rebuilding earthquake damaged roads,
water, wastewater and storm water pipes.



We are 84% through the SCIRT programme.

19 January 2016

Glenstrae retaining wall – Update for January 2016.

As you are aware, Downer as part of SCIRT have been working in your neighbourhood repairing the earthquake damaged retaining wall. This notice is to provide you with details of our repairs over the coming months.

This week we are installing the last two rock anchors into the cliff face for stabilisation. We will then start the first concrete pour for the retaining wall. Over the next month we will be constructing the majority of the retaining wall; placing formwork for the wall, placing the steel reinforcing and pouring concrete at different stages.

We understand there has been some frustration over the lights failing on a couple of occasions. There was a fault with the battery which is now being replaced however if you come across any more issues then please call Spraymarks on 0800 101 373 who will be happy to help.



All works should be complete by March 2016. Happy new year and thank you for your patience.

Need more information? Contact Downer on 0800 400 310 or eqinfo@downer.co.nz



Email: info@scirt.co.nz
www.strongerchristchurch.govt.nz
Follow us on Twitter @SCIRT_info



Programme funded by

New Zealand Government